

Neoprene Bend Sensor + LED circuit

Made from: stretch conductive fabric, conductive thread, fusible interfacing, LED, 2 set of poppers

Necessary components: Neoprene Bend Sensor, Double AA battery pouch, 2 AA batteries




Conductive fabric

— Conductive thread



10mm/15L metal popper



www.KOBAKANT.at

